

Product Change Notification Number: F07/2011

Date: 2011-10-27

Title: Powder cores manufacturing location and I2NC change

Reason for Change:

- | | | |
|--|----------------------------------|------------------------------------|
| <input type="checkbox"/> Production | <input type="checkbox"/> Product | <input type="checkbox"/> Packaging |
| <input checked="" type="checkbox"/> Manufacturing Location | <input type="checkbox"/> Quality | <input type="checkbox"/> Material |
| <input type="checkbox"/> Other | | |

List of Products Subjected to Change:

| 12NC | Reference | 12NC | Reference |
|--------------|------------------|--------------|--------------------|
| 435500121031 | TX10/4-H2-A66 | 435500011245 | TX13/4.8-S7-A34-MC |
| 435500121051 | TX10/4-H2-A84 | 435500011255 | TX13/4.8-S7-A40-MC |
| 435500121131 | TX11/4-H2-A53 | 435500011261 | TX13/4.8-S7-A56 |
| 435500121231 | TX13/4.8-H2-A56 | 435500011265 | TX13/4.8-S7-A56-MC |
| 435500121251 | TX13/4.8-H2-A72 | 435500011331 | TX16/6.4-S7-A35 |
| 435500121321 | TX16/6.4-H2-A35 | 435500011335 | TX16/6.4-S7-A35-MC |
| 435500121331 | TX16/6.4-H2-A72 | 435500011345 | TX16/6.4-S7-A43-MC |
| 435500121351 | TX16/6.4-H2-A92 | 435500011355 | TX16/6.4-S7-A52-MC |
| 435500121421 | TX17/6.4-H2-A43 | 435500011361 | TX16/6.4-S7-A72 |
| 435500121431 | TX17/6.4-H2-A89 | 435500011365 | TX16/6.4-S7-A72-MC |
| 435500121521 | TX20/6.4-H2-A32 | 434100011365 | TX16/6.4-S7-A72-MC |
| 435500121531 | TX20/6.4-H2-A68 | 435500011435 | TX17/6.4-S7-A43-MC |
| 435500121541 | TX20/6.4-H2-A81 | 435500011445 | TX17/6.4-S7-A53-MC |
| 435500121551 | TX20/6.4-H2-A87 | 435500011455 | TX17/6.4-S7-A64-MC |
| 435500121621 | TX23/7.6-H2-A43 | 435500011461 | TX17/6.4-S7-A89 |
| 435500121631 | TX23/7.6-H2-A90 | 435500011465 | TX17/6.4-S7-A89-MC |
| 435500121731 | TX24/8.9-H2-A105 | 435500011531 | TX20/6.4-S7-A32 |
| 435500121721 | TX24/8.9-H2-A51 | 435500011535 | TX20/6.4-S7-A32-MC |
| 435500121831 | TX27/11-H2-A157 | 435500011541 | TX20/6.4-S7-A41 |
| 435500121821 | TX27/11-H2-A75 | 435500011545 | TX20/6.4-S7-A41-MC |
| 435500121931 | TX33/11-H2-A127 | 435500011555 | TX20/6.4-S7-A49-MC |
| 435500121951 | TX33/11-H2-A163 | 435500011561 | TX20/6.4-S7-A68 |
| 435500121921 | TX33/11-H2-A61 | 435500011565 | TX20/6.4-S7-A68-MC |
| 435500122151 | TX36/11-H2-A150 | 435500011611 | TX23/7.6-S7-A19 |
| 435500122231 | TX40/15-H2-A168 | 435500011615 | TX23/7.6-S7-A19-MC |
| 435500122251 | TX40/15-H2-A215 | 435500011631 | TX23/7.6-S7-A43 |
| 435500122221 | TX40/15-H2-A81 | 435500011635 | TX23/7.6-S7-A43-MC |
| 435500122431 | TX47/15-H2-A178 | 435500011641 | TX23/7.6-S7-A54 |
| 435500122321 | TX47/18-H2-A135 | 435500011645 | TX23/7.6-S7-A54-MC |
| 435500122331 | TX47/18-H2-A281 | 435500011651 | TX23/7.6-S7-A65 |
| 435500122731 | TX57/14-H2-A156 | 435500011655 | TX23/7.6-S7-A65-MC |
| 435500122721 | TX57/14-H2-A75 | 435500011661 | TX23/7.6-S7-A90 |
| 435500120431 | TX6.6/2.5-H2-A54 | 435500011665 | TX23/7.6-S7-A90-MC |
| 435500120451 | TX6.6/2.5-H2-A69 | 435500011761 | TX24/8.9-S7-A105 |

| | | | |
|--------------|------------------|--------------|---------------------|
| 435500122821 | TX78/13-H2-A68 | 435500011765 | TX24/8.9-S7-A105-MC |
| 435500122961 | TX78/16-H2-A178 | 435500011715 | TX24/8.9-S7-A22-MC |
| 435500122931 | TX78/16-H2-A178 | 435500011735 | TX24/8.9-S7-A51-MC |
| 435500022911 | TX78/16-H2-A37 | 435500011745 | TX24/8.9-S7-A63-MC |
| 435500035081 | TC10/4-M2-A159 | 435500011755 | TX24/8.9-S7-A76-MC |
| 435500034051 | TC3.6/1.5-M2-A33 | 435500011851 | TX27/11-S7-A113 |
| 435500034171 | TC3.9/2.5-M2-A56 | 435500011855 | TX27/11-S7-A113-MC |
| 435500131071 | TX10/4-M2-A105 | 435500011861 | TX27/11-S7-A157 |
| 435500131031 | TX10/4-M2-A66 | 435500011865 | TX27/11-S7-A157-MC |
| 435500131121 | TX11/4-M2-A26 | 435500011811 | TX27/11-S7-A32 |
| 435500131131 | TX11/4-M2-A53 | 435500011815 | TX27/11-S7-A32-MC |
| 435500131171 | TX11/4-M2-A85 | 435500011831 | TX27/11-S7-A75 |
| 435500131281 | TX13/4.8-M2-A134 | 435500011835 | TX27/11-S7-A75-MC |
| 435500131221 | TX13/4.8-M2-A27 | 435500011841 | TX27/11-S7-A94 |
| 435500131231 | TX13/4.8-M2-A56 | 435500011845 | TX27/11-S7-A94-MC |
| 435500131251 | TX13/4.8-M2-A72 | 435500011961 | TX33/11-S7-A127 |
| 435500131261 | TX13/4.8-M2-A79 | 435500011965 | TX33/11-S7-A127-MC |
| 435500131271 | TX13/4.8-M2-A90 | 435500011911 | TX33/11-S7-A28 |
| 435500131361 | TX16/6.4-M2-A104 | 435500011915 | TX33/11-S7-A28-MC |
| 435500131371 | TX16/6.4-M2-A115 | 435500011931 | TX33/11-S7-A61 |
| 435500131381 | TX16/6.4-M2-A173 | 435500011935 | TX33/11-S7-A61-MC |
| 435500131321 | TX16/6.4-M2-A35 | 435500011945 | TX33/11-S7-A76-MC |
| 435500131331 | TX16/6.4-M2-A72 | 435500011951 | TX33/11-S7-A91 |
| 435500131341 | TX16/6.4-M2-A88 | 435500011955 | TX33/11-S7-A91-MC |
| 435500131351 | TX16/6.4-M2-A92 | 435500012015 | TX34/8.9-S7-A16-MC |
| 435500131421 | TX17/6.4-M2-A43 | 435500012035 | TX34/8.9-S7-A38-MC |
| 435500131431 | TX17/6.4-M2-A89 | 435500012045 | TX34/8.9-S7-A47-MC |
| 435500131581 | TX20/6.4-M2-A163 | 435500012055 | TX34/8.9-S7-A57-MC |
| 435500131521 | TX20/6.4-M2-A32 | 435500012065 | TX34/8.9-S7-A79-MC |
| 435500131531 | TX20/6.4-M2-A68 | 435500012161 | TX36/11-S7-A117 |
| 435500131551 | TX20/6.4-M2-A87 | 435500012165 | TX36/11-S7-A117-MC |
| 435500131651 | TX23/7.6-M2-A115 | 435500012111 | TX36/11-S7-A24 |
| 435500131671 | TX23/7.6-M2-A144 | 435500012115 | TX36/11-S7-A24-MC |
| 435500031611 | TX23/7.6-M2-A19 | 435500012131 | TX36/11-S7-A56 |
| 435500131681 | TX23/7.6-M2-A216 | 435500012135 | TX36/11-S7-A56-MC |
| 435500131621 | TX23/7.6-M2-A43 | 435500012141 | TX36/11-S7-A70 |
| 435500131631 | TX23/7.6-M2-A90 | 435500012145 | TX36/11-S7-A70-MC |
| 435500131731 | TX24/8.9-M2-A105 | 435500012155 | TX36/11-S7-A84-MC |
| 435500031711 | TX24/8.9-M2-A22 | 435500012241 | TX40/15-S7-A101 |
| 435500131721 | TX24/8.9-M2-A51 | 435500012245 | TX40/15-S7-A101-MC |
| 435500131831 | TX27/11-M2-A157 | 435500012251 | TX40/15-S7-A121 |
| 435500031801 | TX27/11-M2-A18 | 435500012255 | TX40/15-S7-A121-MC |
| 435500131861 | TX27/11-M2-A217 | 435500012261 | TX40/15-S7-A168 |
| 435500131871 | TX27/11-M2-A251 | 435500012265 | TX40/15-S7-A168-MC |
| 435500031811 | TX27/11-M2-A32 | 435500012211 | TX40/15-S7-A35 |
| 435500131881 | TX27/11-M2-A377 | 435500012215 | TX40/15-S7-A35-MC |
| 435500131821 | TX27/11-M2-A75 | 435500012231 | TX40/15-S7-A81 |

| | | | |
|--------------|---------------------|--------------|---------------------|
| 435500130181 | TX3.9/2.5-M2-A84 | 435500012235 | TX40/15-S7-A81-MC |
| 435500131931 | TX33/11-M2-A127 | 435500012445 | TX47/15-S7-A107-MC |
| 435500131951 | TX33/11-M2-A163 | 435500012455 | TX47/15-S7-A128-MC |
| 435500131971 | TX33/11-M2-A203 | 435500012461 | TX47/15-S7-A178 |
| 435500131921 | TX33/11-M2-A61 | 435500012465 | TX47/15-S7-A178-MC |
| 435500132121 | TX36/11-M2-A56 | 435500012411 | TX47/15-S7-A37 |
| 435500130231 | TX4.7/2.5-M2-A42 | 435500012415 | TX47/15-S7-A37-MC |
| 435500130281 | TX4.7/2.5-M2-A99 | 435500012431 | TX47/15-S7-A86 |
| 435500132231 | TX40/15-M2-A168 | 435500012435 | TX47/15-S7-A86-MC |
| 435500132271 | TX40/15-M2-A269 | 435500012331 | TX47/18-S7-A135 |
| 435500032211 | TX40/15-M2-A35 | 435500012335 | TX47/18-S7-A135-MC |
| 435500132221 | TX40/15-M2-A81 | 435500012341 | TX47/18-S7-A169 |
| 435500032411 | TX47/15-M2-A37 | 435500012345 | TX47/18-S7-A169-MC |
| 435500132321 | TX47/18-M2-A135 | 435500012355 | TX47/18-S7-A202-MC |
| 435500132331 | TX47/18-M2-A281 | 435500012361 | TX47/18-S7-A281 |
| 435500032311 | TX47/18-M2-A59 | 435500012365 | TX47/18-S7-A281-MC |
| 435500132521 | TX51/14-M2-A73 | 435500012311 | TX47/18-S7-A59 |
| 435500132731 | TX57/14-M2-A156 | 435500012315 | TX47/18-S7-A59-MC |
| 435500132761 | TX57/14-M2-A218 | 435500012555 | TX51/14-S7-A109-MC |
| 435500132771 | TX57/14-M2-A250 | 435500012561 | TX51/14-S7-A152 |
| 435500032711 | TX57/14-M2-A33 | 435500012565 | TX51/14-S7-A152-MC |
| 435500132721 | TX57/14-M2-A75 | 435500012515 | TX51/14-S7-A32-MC |
| 435500130381 | TX6.4/2.8-M2-A120 | 435500012531 | TX51/14-S7-A73 |
| 435500130331 | TX6.4/2.8-M2-A50 | 435500012535 | TX51/14-S7-A73-MC |
| 435500130431 | TX6.6/2.5-M2-A54 | 435500012545 | TX51/14-S7-A91-MC |
| 435500130451 | TX6.6/2.5-M2-A69 | 435500012755 | TX57/14-S7-A112-MC |
| 435500130471 | TX6.6/2.5-M2-A86 | 435500012761 | TX57/14-S7-A156 |
| 435500130531 | TX6.6/4.8-M2-A103 | 435500012765 | TX57/14-S7-A156-MC |
| 435500130561 | TX6.6/4.8-M2-A144 | 435500012711 | TX57/14-S7-A33 |
| 435500130571 | TX6.6/4.8-M2-A165 | 435500012715 | TX57/14-S7-A33-MC |
| 435500130581 | TX6.6/4.8-M2-A247 | 435500012731 | TX57/14-S7-A75 |
| 435500130781 | TX7.9/3.2-M2-A124 | 435500012735 | TX57/14-S7-A75-MC |
| 435500130731 | TX7.9/3.2-M2-A52 | 435500012745 | TX57/14-S7-A94-MC |
| 435500130771 | TX7.9/3.2-M2-A83 | 435500012631 | TX57/15-S7-A138 |
| 435500032801 | TX78/13-M2-A16 | 435500012635 | TX57/15-S7-A138-MC |
| 435500132871 | TX78/13-M2-A225 | 435500012645 | TX57/15-S7-A172-MC |
| 435500032811 | TX78/13-M2-A30 | 435500012655 | TX57/15-S7-A207-MC |
| 435500130881 | TX9.7/3.2-M2-A128 | 435500012661 | TX57/15-S7-A287 |
| 435500130871 | TX9.7/3.2-M2-A84 | 435500012665 | TX57/15-S7-A287-MC |
| 435500130981 | TX9.7/4-M2-A159 | 435500012611 | TX57/15-S7-A60 |
| 435500130931 | TX9.7/4-M2-A66 | 435500012615 | TX57/15-S7-A60-MC |
| 435500014061 | TC3.6/1.5-S7-A26 | 435500010361 | TX6.4/2.8-S7-A50 |
| 435500014361 | TC6.4/2.8-S7-A50 | 433000010361 | TX6.4/2.8-S7-A50 |
| 435500014761 | TC7.9/3.2-S7-A52 | 435500010735 | TX7.9/3.2-S7-A25-MC |
| 435500014765 | TC7.9/3.2-S7-A52-MC | 435500010745 | TX7.9/3.2-S7-A31-MC |
| 435500011035 | TX10/4-S7-A32-MC | 435500010755 | TX7.9/3.2-S7-A37-MC |
| 435500011045 | TX10/4-S7-A40-MC | 435500010761 | TX7.9/3.2-S7-A52 |

| | | | |
|--------------|--------------------|--------------|---------------------|
| 435500011055 | TX10/4-S7-A48-MC | 435500010765 | TX7.9/3.2-S7-A52-MC |
| 435500011061 | TX10/4-S7-A66 | 435500012811 | TX78/13-S7-A30 |
| 435500011065 | TX10/4-S7-A66-MC | 435500012911 | TX78/16-S7-A37 |
| 435500011131 | TX11/4-S7-A26 | 435500010835 | TX9.7/3.2-S7-A25-MC |
| 435500011135 | TX11/4-S7-A26-MC | 435500010845 | TX9.7/3.2-S7-A32-MC |
| 435500011145 | TX11/4-S7-A32-MC | 435500010855 | TX9.7/3.2-S7-A38-MC |
| 435500011155 | TX11/4-S7-A38-MC | 435500010861 | TX9.7/3.2-S7-A53 |
| 435500011161 | TX11/4-S7-A53 | 435500010865 | TX9.7/3.2-S7-A53-MC |
| 435500011165 | TX11/4-S7-A53-MC | 435500010935 | TX9.7/4-S7-A32-MC |
| 435500011231 | TX13/4.8-S7-A27 | 435500010945 | TX9.7/4-S7-A40-MC |
| 435500011235 | TX13/4.8-S7-A27-MC | 435500010955 | TX9.7/4-S7-A48-MC |
| 435500011241 | TX13/4.8-S7-A34 | 435500010965 | TX9.7/4-S7-A66-MC |

Change Description: All the powder cores, including references listed above, change their manufacturing location (from Spain to Poland) and I2NC. The change will be effective from January 2012 onwards.