

The FA2443-AL was developed specifically for Texas Instruments UCC28600 Quasi-Resonant Flyback Green Mode Controller and is specified in SLUU256A for the evaluation module. This transformers is designed to operate in discontinous conduction mode at frequencies up to 140 kHz.

Coilcraft can also custom engineer a transformer to meet your specific requirements.

For free evaluation samples, contact Coilcraft or visit www.coilcraft.com.

Core material Ferrite

Terminations RoHS tin-silver over tin over nickel over phos bronze. Other terminations available at additional cost.

Weight 89.2 g

Ambient temperature -40°C to +85°C

Storage temperature Component: -40°C to +85°C. Packaging: -40°C to +80°C

Moisture Sensitivity Level (MSL) 1 (unlimited floor life at <30°C / 85% relative humidity)

Failures in Time (FIT) / Mean Time Between Failures (MTBF) 38 per billion hours / 26,315,789 hours, calculated per Telcordia SR-332 Packaging 50 parts per tray

PCB washing Only pure water or alcohol recommended

| Part number | Inductance at 0 A ¹ ±10% (µH) | Inductance at Ipk ² min (µH) | DCR max (Ohms) | Leakage inductance ³ max (µH) | Turns pri : sec ⁴ | s ratio pri : bias | Ipk ² (A) | lsolation⁵ Vrms | Output |
|----------------|--|---|--|--|---------------------------------|-----------------------|--------------------------------|--------------------|--------|
| FA2443-AL | 200 | 162 | 0.217 (4-6) 0.020 (8-13) 0.020 (9-14) 0.515 (1-7) | 5.9 | 6:1 | 6:1 | 6.0 | 1500 | 120 W |

1. Inductance is for the primary, measured at 10 kHz, 0.1 Vrms, 0 Adc.

2. Peak primary current drawn at minimum input voltage.

3. Leakage inductance is for the primary and is measured at 100 kHz, 0.1 Vrms with all other windings shorted.

4. Turns ratio for the secondary is with the windings connected in parallel

5. Isolation is from the primary to all other windings.

4 C

6. Electrical specifications at 25°C.

Refer to Doc 362 "Soldering Surface Mount Components" before soldering.





Dimensions are in inches





Specifications subject to change without notice. Please check our website for latest information.

Document 539 Revised 10/28/08

1102 Silver Lake Road Carv. Illinois 60013 Phone 847/639-6400 Fax 847/639-1469 E-mail info@coilcraft.com Web http://www.coilcraft.com

6 C



08

09

Secondary windings to be connected in parallel on the PC board